Project: Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

G.E.105

Inspection Date:

14.03.19

Location:

Plant Room

Level:

00 - Ground Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

Aluminium air pump x 1

~

No.

Bora Blower

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 4

See Section 1.4.2 for details

Economic Life:

15

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

< 5

Years

Comments:

The air blower remains as per report back in 2015. Operation of air blower unknown as this was not in use during inspection.

Inspection Date:

22

Purley Leisure Centre, Croydon Project:

G.E.111

Asset Register

14.03.19

Plant Room Location:

00 - Ground Floor

Level:

Equipment / Plant Ref:

Model Type:

Asset Reference:

Quantity:

Manufacturer:

Serial No:

Trend BMS IQE View panel

Located on the front panel of the Control panel in the Plantroom

Trend

Not available





See Section 1.4.2 for details

Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 4

From new/installation assuming regular Economic Life: 20 Year

servicing/maintenance

Predicated Future Life: <2 Years

> The plant is in operation therefore we deem the control panel to be operating sufficiently. However we do not deem it to be operating in an energy efficient manner due to age and deterioration of sensors and control hardware.

Comments: We understand the Controls and wiring are in excess of 25 years old.

> Replacements of the BMS would see benefit to user in terms of efficiency, operation, running cost reductions through improved serivces management.

Project: Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

G.E.113

Inspection Date:

14.03.19

Location:

Plant Room

Level:

00 - Ground Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

Nuaire fan 1 and 2 AHU control panel

~ 1

No.

Nuaire

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 4

See Section 1.4.2 for details

Economic Life:

10 to 15

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

< 2

Years

Comments:

The controls are beyond their economical life.

Project: Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

G.E.114

Inspection Date:

14.03.19

Location:

Plant Room

Level:

00 - Ground Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

Eiohurst BMS lan M/Box control panel

~

No.

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 4

See Section 1.4.2 for details

Economic Life:

10 to 15

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

< 2

Years

Comments:

The controls are beyond their economical life.

55	Project:	Purley Leisure Centre, Croydon	Asset Register
	Asset Reference:	G.E.38 Inspection Date:	17.07.15
	Location: Level:	ITC room - 08 00 - Ground Floor	
	Equipment / Plant Ref: Model Type: Quantity: Manufacturer: Serial No:	Convector heater x 1 Unknown ? No. ?	
		No access during inspection	
	Condition Rating:	See section 1.4.1 for grading details	
	Priority Grading:	See Section	on 1.4.2 for details
	Economic Life:	10 to 20 Year From new/installation assuming regular servicing/maintenance	
	Predicated Future Life:	Years	
	Comments:	Room not accessed during inspection	

Project: Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

G.M.30

Inspection Date:

14.03.19

Location:

Plant Room - Room 12

Level:

00 - Ground Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

Calorifiers DHWS

2m high x 1m daimeter calorifiers with internal primary coils

N

Unknown

Not available





Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

25

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

<3

Years

Comments:

Annual risk assessment is carried out by others on the domestic systems as part of the Legionella check. We have not seen latest report as of 2019. Last report by Aquatech Environmental Services Ltd 13.02.2013 due for renewal 2015.

Temperature gauges faulty. Fair condition for its age.

Project: Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

G.M.35

Inspection Date:

14.03.19

Location:

Plant Room - Room 12

Level:

00 - Ground Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

Circulating pumps DHS secondary pumps 1 & 2

Single head circulating pumps installed in parrallel

No

Grundfos - 25-50/2

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 3 to 2

See Section 1.4.2 for details

Economic Life:

10 to 20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

< 2

Years

Comments:

Showing signs of corrsion from the pump seals and casing.

Project: Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

G.M.37

Inspection Date:

14.03.19

Location:

Plant Room - Room 12

Level:

00 - Ground Floor

Equipment / Plant Ref:

Heating secondary pumps

Model Type:

Belt driven

Quantity:

Not available from site survey

Manufacturer: Serial No:

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 2

See Section 1.4.2 for details

Economic Life:

20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

<2

Years

Comments:

Pump showing major signs of corrosion to casing. Appears belt have been replaced recently. No speed control on the pump set.

Project:	Purley Leisure Centre, Croydon	Asset Register
Asset Reference:	1.E.16 Inspection Date:	14.03.19
Location: Level:	Changing room - 27 01 - First Floor	
Equipment / Plant Ref: Model Type: Quantity: Manufacturer: Serial No:	Convector blow heater Dimplex 1 No. Dimplex Not available	
Condition Rating:	Grade B See section 1.4.1 for grading details	
Priority Grading:	Priority 4 See Section	on 1.4.2 for details
Economic Life:	Year From new/installation assuming regular servicing/maintenance	
Predicated Future Life:	2 to 4 Years	
Comments:	~	

Project:	Purley Leisure Centre, Croydon	Asset Register
Asset Reference:	1.E.34 Inspection Date:	14.03.19
Location: Level:	Public gallery - 50 01 - First Floor	
Equipment / Plant Ref: Model Type: Quantity: Manufacturer: Serial No:	Extractor fan Dimplex 1 No. ? ?	
Condition Rating:	See section 1.4.1 for grading details	
Priority Grading:	See Section	n 1.4.2 for details
Economic Life:	? Year From new/installation assuming regular servicing/maintenance	
Predicated Future Life:	? Years	
Comments:	Fan not located during inspection	

Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

2.M.1

Inspection Date:

14.03.19

Location:

Room 53

Level:

02 - Second Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

AHU 4 Teaching pool - supply & extract

AHU No. 4 supply & extract fans

No.

Not available from site survey

Not available





Condition Rating:

Grade A

See section 1.4.1 for grading details

Supply & Return Air Ducts require insulation.

Priority Grading:

Priority 4

See Section 1.4.2 for details

Economic Life:

20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

18

Years

AHU 4 and 5 have been replaced within the past 2 years. However the ductwork, pipework and controls associated remain as existing.

Comments:

Replacement of the HVAC generally associated (pipework control valves, sensors, control panel, etc) with the new AHU would see significant improvements.

None of the Ductwork in the Plantroom seems to be insulated. At least the Intake,

2.M.10

Asset Register

14.03.19

Level: 02 - Second Floor

Asset Reference:

Location:

Equipment / Plant Ref: AHU7 Supply & extract unit

Model Type:

Belt drive fans 4 x SP21180 & 1060, washable sponge filter, re-heat

Changing Room Plant Room 52

battery

Quantity: 1 No.

Manufacturer: Not available from site survey

Serial No: Not available





Inspection Date:

Condition Rating: Grade B

Comments:

See section 1.4.1 for grading details

Priority Grading: See Section 1.4.2 for details

Economic Life: Year From new/installation assuming regular servicing/maintenance

Predicated Future Life: 2 to 5 Years Fan: >12 years Years

The Fan has been replaced within the past 2 years. However the AHU casing etc is still in poor condition along with associated HVAC.

Replacement of the HVAC generally associated (pipework control valves, sensors, control panel, etc) with the new AHU would see significant improvements.

Only a small amount of Ductwork in the Plantroom seems to be insulated. At least

the Intake, Supply & Return Air Ducts require insulation.

Suggest deep cleaning of internal ductwork and grilles from which the unit is

served to reduce resistance.

Unit requires full internal clean and service.

Purley Leisure Centre, Croydon Project:

Asset Register

Asset Reference:

2.M.14

Inspection Date:

14.03.19

Location:

Changing Room Plant Room 52

Level:

02 - Second Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

AHU7 changing room control panel

1

No.

MS (Main Systems)

Not available



Condition Rating:

Grade C

See section 1.4.1 for grading details

Priority Grading:

Priority 2

See Section 1.4.2 for details

Economic Life:

10-20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

1

Years

Comments:

The panel itself is at the end of economical life and appears to have had components removed. We would surmise that it is now used solely as an isolator

for the AHU.

Asset Register

Asset Reference:

2.M.2

Inspection Date:

14.03.19

Location:

Room 53

Level:

02 - Second Floor

Equipment / Plant Ref:

AHU 5 teaching pool void - supply

Model Type:

AHU supply - filter section & heater battery

Quantity:

l No.

Manufacturer:

Not available from site survey

Serial No:

Not available





Condition Rating:

Grade A

See section 1.4.1 for grading details

Priority Grading:

Priority 4

See Section 1.4.2 for details

Economic Life:

20

From new/installation assuming regular

servicing/maintenance

Predicated Future Life:

20

Years

Year

AHU 4 and 5 have been replaced within the past 2 years. However the ductwork, pipework and controls associated remain as existing.

Comments:

Replacement of the HVAC generally associated (pipework control valves, sensors, control panel, etc) with the new AHU would see significant improvements. None of the Ductwork in the Plantroom seems to be insulated. At least the Intake, Supply & Return Air Ducts require insulation.

Asset Register

Asset Reference:

2.M.6

Inspection Date:

14.03.19

Location:

Room 53

1

Level:

02 - Second Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

Pool humidity alarm panel

No.

MS (Main Systems)

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

15 to 20

Year

From new/installation assuming regular

servicing/maintenance

Predicated Future Life:

<2

Years

Comments:

Condition of the panel is satisfactory and fair for its age.

Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

2.M.7

Inspection Date:

14.03.19

Location:

Room 53

Level:

02 - Second Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Manufacturer

Serial No:

AHU 4 & 5 control panel

No.

Trend

1

Not available



Condition Rating:

Grade C

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

15 to 20

Year

From new/installation assuming regular

servicing/maintenance

Predicated Future Life:

< 2

Years

Comments:

The panel currently allows the AHU to operate. We do not envisage that the controls provide energy efficient control.

Project: Purley Leisure Centre, Croydon Asset Register

Asset Reference: 2.M.9 Inspection Date: 14.03.19

Location: External Flat Roof Area

Level: 02 - Second Floor

Equipment / Plant Ref: Mitsubishi air conditioner condenser outdoor units - max

electrical load 15 amp

Model Type: FDC100VS

Quantity: 3 No.

Manufacturer: Mitsubishi Heavy Industries

AB2900282UF

Serial No: (newer unit),

A18501406 RF & A18501159RF



Condition Rating: Grade A(1 unit) & B(2 units)

Predicated Future Life:

See section 1.4.1 for grading details

Priority Grading: Priority 4 See Section 1.4.2 for details

Economic Life: Year From new/installation assuming regular servicing/maintenance

10

Unit 1 – installed in 2017 looks in good working condition.

Years

Comments: Units 2 & 3 – installed in 2013. The appearance of the external condensers is

fair for its age. We would suggest units are serviced to ensure condensers are operating as efficiently as possible (services to include re-gassing units).

Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

3.M.2

Inspection Date:

14.03.19

Location:

Room 54

Level:

03 - Third Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

AHU6 disabled toilets & changing rooms supply belt drive

frost & reheat heater batteries, filter section

No.

Not available from site survey

Not available





Condition Rating:

Grade B/C

See section 1.4.1 for grading details

Priority Grading:

Priority 3/4

See Section 1.4.2 for details

Economic Life:

20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

2 to 5

Years

The Fan has been replaced within the past 2 years. However the AHU casing etc is still in poor condition along with associated HVAC.

Replacement of the HVAC generally associated (pipework control valves, sensors, control panel, etc) with the new AHU would see signifcant improvements.

Comments:

Majority of the Ductwork insulation is currently falling apart, with a considerable length of ductwork without any insulation. At least the Intake, Supply & Return

Air Ducts require insulation. Unit requires full internal clean and service.

Asset Register

3.M.3

Inspection Date:

14.03.19

Location:

Room 54

Level:

03 - Third Floor

Equipment / Plant Ref:

Asset Reference:

AHU disabled toilets & changing room extract system

Model Type:

^

Quantity:

1 No.

Manufacturer:

Not available from site survey

Serial No:

Not available





Condition Rating:

Grade B/C

See section 1.4.1 for grading details

Priority Grading:

Priority 3/4

See Section 1.4.2 for details

Economic Life:

20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

1 to 5

Years

Comments:

Extract unit replaced within past 6 years.

HVAC generally is in a poor state.

Asset Register

Asset Reference:

3.M.5

Inspection Date:

14.03.19

Location:

Room 54

Level:

03 - Third Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

AHU disabled toilet & changing room control panel x 1

1

No.

Main Systems

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

15 to 20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

5

Years

Comments:

Project:	Purley Leisure C	entre, Croydon	As	sset Register
Asset Reference:	4.M.1] 1	nspection Date:	14.03.19
Location: Level:	External roof 04 - Fourth Floor			
Equipment / Plant Ref: Model Type: Quantity: Manufacturer: Serial No:	Condensers x 2 4kW 2 No. Toshiba 74280130			
	No photo taken durir	ng inspection		
Condition Rating:	Grade B See section 1.4.1 fo	r grading details		
Priority Grading:	Priority 4		See Section 1.	4.2 for details
Economic Life:	20 Year	From new/installation ass servicing/maintenance	suming regular	
Predicated Future Life:	5 Years			
Comments:	~			

Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

4.M.10

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

BMS panel

..

No.

Trend

Not available







Condition Rating:

Grade C

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

10 to 15

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

1 to 3

Years

Comments:

No change - Whilst boiler and plant are operating we do not deem them to be operating efficiently. The controls are past their economical expected life. Spare parts for the plant/equipment may become obsolete.

Asset Register

Asset Reference:

4.M.11

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

Boiler cycling control panel

Model Type:

1

Quantity:

No.

Manufacturer:

EGS

Serial No:

Not available





Condition Rating:

Grade C

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

10 to 15 Ye

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

1 to 3

Years

Comments:

No change - Whilst boiler and plant are operating we do not deem them to be operating efficiently.

Purley Leisure Centre, Croydon Project:

Asset Register

Asset Reference:

4.M.12

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

Boiler control panel

Model Type:

1

Quantity:

No.

Manufacturer:

Main systems

Serial No:

Not available





Condition Rating:

Grade C

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

10 to 15

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

1 to 3

Years

Comments:

No change - Whilst boiler and plant are operating we do not deem them to be operating efficiently.

Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

4.M.13

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

Mechanical gas shut off emergency system

Model Type:

Drop weight isolation valve from fuseable link to each boiler plant

Quantity:

No

Manufacturer:

Not available from site survey

Serial No:

Not available





Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 4

See Section 1.4.2 for details

Economic Life:

25

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

5

Years

No change - The operation of the valve should be checked along with annual gas servicing.

Comments:

Should boilers be replaced we would suggest solenoid valve is installed in leiu of drop weight valve arrangement.

Project: Purley Leisu

Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

4.M.14

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

Pool humidity alarm panel

Model Type:

~ 1

Quantity:

No.

Manufacturer:

Main systems

Serial No:

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 4

See Section 1.4.2 for details

Economic Life:

20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

2 to 5

Years

Comments:

No change - The humidity alarm operation is unknown.

Project:	Purley Leisure Centre, Croydon	Ass	et Register
Asset Reference:	4.M.15 Ins	spection Date:	17.07.15
Location: Level:	Boiler room - 56 04 - Fourth Floor		
Equipment / Plant Ref: Model Type: Quantity: Manufacturer: Serial No:	System dosing pot 1 No. JET Not available		
	No picture taken during inspection.		
Condition Rating:	Grade B		
	See section 1.4.1 for grading details		
Priority Grading:	Priority 4	See Section 1.4	.2 for details
Economic Life:	Year From new/installation assume servicing/maintenance	ıming regular	
Predicated Future Life:	5 Years		
Comments:	Unit is in fair condition for its age.		

Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

4.M.17

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

Model Type:

D125 1

Quantity:

No.

System pressurisation unit

Manufacturer:

JET digital plus

Serial No:

Not available





Condition Rating:

Grade C

See section 1.4.1 for grading details

Priority Grading:

Priority 2

See Section 1.4.2 for details

Economic Life:

20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

2 to 5

Years

Comments:

Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

4.M.18

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

System pressurisation unit

800 ltr buffer vessel 5.0 bar

1

No.

Pullen pumps

SP87216





Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

15

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

2 to 5

Years

Comments:

No change - Pressure gauge reading 1.3 bar during inspection Spare parts for the plant/equipment may become obsolete.

Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

4.M.2

Inspection Date:

14.03.19

Location:

External roof

Level:

04 - Fourth Floor

Equipment / Plant Ref:

AHU Main pool supply and extract

Model Type:

Belts Size 4 x SPZ 1800, frost & reheat batteries, filters

Quantity:

No.

Manufacturer:

Not available from site survey

Serial No:

Not available











Condition Rating:

Grade D

See section 1.4.1 for grading details

Priority Grading:

Priority 1

See Section 1.4.2 for details

Economic Life:

20

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

0

Years

Year

Pool Unit No 1 is not opperational. Failure of other units would mean closure of the Pool as a suitable conditon within could not be met.

Comments:

Compared with units installed at new Pools the operation is extremely inefficient. The units show signs of extreme corrosion which in some instances have been repaired.

Asset Register

Asset Reference:

4.M.20

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

Combined heat and power unit

Model Type:

Gas fired CHP

Quantity:

No.

Manufacturer:

Combined Power Systems

Serial No:

Not available





Condition Rating:

Grade D

See section 1.4.1 for grading details

Priority Grading:

Priority 1

See Section 1.4.2 for details

Economic Life:

20

From new/installation assuming regular

servicing/maintenance

Predicated Future Life:

Offline

Years

Year

Comments:

This unit has been decommissioned and understand has not run for >15 years. It is not deemed that the unit is essential as part of the operation, it would improve heating efficiency and lower the buildings overall carbon footprint.

Asset Register

Asset Reference:

4.M.21

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

MTHW pump close coupled

Model Type:

2.2kw

Quantity:

No.

Manufacturer:

Lowara

Serial No:

PLM4100B 553/322





Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 4

See Section 1.4.2 for details

Economic Life:

20

Year

From new/installation assuming regular

servicing/maintenance

Predicated Future Life:

5 to 8

Years

Comments:

The pump is in good condition.

Purley Leisure Centre, Croydon Project:

4.M.22

Asset Register

14.03.19

Location: Boiler room - 56

Level: 04 - Fourth Floor

Equipment / Plant Ref: MTHW pump close coupled x 1

Model Type: 3.0kw

Quantity:

Asset Reference:

No.

Manufacturer: **Brook Hansen**

Serial No: P907353





Inspection Date:

Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading: Priority 3

See Section 1.4.2 for details

Economic Life:

20 Year From new/installation assuming regular

servicing/maintenance

Predicated Future Life:

Years

Comments:

Belts and pulleys appear in good condition. The pump is belt driven and we deem belts are changed regulary as and when they fail or show signs of wear.

2525			
3535	Project:	Purley Leisure Centre, Croydon	Asset Register
	Asset Reference:	4.M.5 Inspection	on Date: 14.03.19
	Location: Level:	External roof 04 - Fourth Floor	
	Equipment / Plant Ref: Model Type: Quantity: Manufacturer: Serial No:	AHU control panel section	
		~	
	Condition Rating:	See section 1.4.1 for grading details	
	Priority Grading:	Se	ee Section 1.4.2 for details
	Economic Life:	10 to 15 Year From new/installation assuming servicing/maintenance	g regular
	Predicated Future Life:	5 Years	
	Comments:	Not located during survey. The AHU's are operating	g currently.

Asset Register

Asset Reference:

4.M.6

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

Boilers

Model Type:

SCP200 gas fired

Quantity:

No.

Manufacturer:

Hartley & Sugden

Serial No:

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

25

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

<5 years

Years

The boilers are original and in fair condition.

The Burners on the 2 No. Boilers have been replaced with new Riello burners within the last 2 years.

Comments:

Replacement of the boilers, control valves & sensors would provide improved efficiency in terms of running costs and energy use.

Spare parts for the plant/equipment may become obsolete.

Pipework insulation is falling apart in some locations and needs to be replaced.

Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

4.M.7

Inspection Date:

14.03.19

Location:

Boiler room - 56

Level:

04 - Fourth Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

Boiler flue systems / insulated

s/s to high level


2

No.

Hartley & Sugden

Not available





Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 3/2

See Section 1.4.2 for details

Economic Life:

15 to 30 Year

From new/installation assuming regular

servicing/maintenance

Predicated Future Life:

<5 year

Years

Comments:

The flues are showing signs of corrosion and should be checked annually as part of the gas aafe checks undertaken.

6.M.1

Asset Register

Inspection Date:

14.03.19

Location:

Asset Reference:

Cold Water Tank Room

Level:

06 - Sixth Floor

Equipment / Plant Ref:

Cold water services storage tanks

Model Type:

3,000 litres approx each tank

Quantity:

3 No.

Manufacturer:

Braithwaite

Serial No:

Not available





Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 2

See Section 1.4.2 for details

Economic Life:

25

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

<5

Years

Comments:

Annual risk assessment is carried out by others on the domestic systems as part of the Legionella check. We have not seen recent report as of 2019, the report by Aquatech Environmental Services Ltd 13.02.2013 due for renewal 2015. The insulation to the tanks is showing signs of age.

Pipework could be upgraded to improve effectiveness.

Asset Register

Asset Reference:

6.M.12

Inspection Date:

14.03.19

Location:

Cold Water Tank Room

Level:

06 - Sixth Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

Metering pumps within Tristel VG2000 system

Chlorine dioxide dosing system

No.

Grundfos

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 4

See Section 1.4.2 for details

Economic Life:

20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

2 to 5

Years

Comments:

The pumps appear in fair condition for their age and appear to be operating with no alarm indication.

Asset Register

Asset Reference:

6.M.3

Inspection Date:

14.03.19

Location:

Cold Water Tank Room

Level:

06 - Sixth Floor

Equipment / Plant Ref:

Cold water service incoming supply service pipe

Model Type:

32 diameter

Quantity:

No.

Manufacturer:

Not available from site survey

Serial No:

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

<5

Years

Comments:

Meter is in good condition with no major signs of deterioration. Water sample analysis should be undertaken to deem quality of water supplied.

Purley Leisure Centre, Croydon Asset Register Project: Asset Reference: 6.M.5 Inspection Date: 14.03.19 Cold Water Tank Room Location: 06 - Sixth Floor Level: Equipment / Plant Ref: Cold water services incoming supply stopcock Model Type: Stop Valve 1 No. Quantity: Manufacturer: Hattersley Serial No: Not available **Grade B Condition Rating:** See section 1.4.1 for grading details **Priority 3 Priority Grading:** See Section 1.4.2 for details From new/installation assuming regular Economic Life: 20 Year servicing/maintenance Predicated Future Life: 5 Years

Operation of valve to be checked

Comments:

Asset Register

Asset Reference:

6.M.7

Inspection Date:

14.03.19

Location:

Cold Water Tank Room

Level:

06 - Sixth Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

Frost protection heaters

No.

Wall mounted radiant tube heaters

Thermotube

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

10

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

1 to 3

Years

Comments:

Operation of heaters to be checked

Asset Register

Asset Reference:

6.M.9

Inspection Date:

14.03.19

Location:

Cold Water Tank Room

Level:

06 - Sixth Floor

Equipment / Plant Ref:

Small GRP header tank x 1

Model Type:

Manufacturer:

250 litre - GRP

Quantity:

Not available from site survey

No.

Serial No:

Not available



Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 4

See Section 1.4.2 for details

Economic Life:

25

Year

From new/installation assuming regular

servicing/maintenance

Predicated Future Life:

5

Years

Comments:

Tank is in fair condtion, un-insulated - non potable.

Project: Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

8.M.1

Inspection Date:

14.03.19

Location:

Plant room

Level:

08 - Eighth Floor

AHU small pool extracts

No.

Equipment / Plant Ref:

Model Type:

TPN fan

Quantity:

2

Manufacturer:

Nuaire

Serial No:

2807054





Condition Rating:

Grade C

See section 1.4.1 for grading details

Priority Grading:

Priority 2

See Section 1.4.2 for details

Economic Life:

20

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

1 to 3

Years

Comments:

2015 Notes - There were two fans installed in the plant room. During inspection one of the units was 'rattling' suggest they are serviced and ductwork internally cleaned to reduce resistance on fan unit.

Project: Purley Leisure Centre, Croydon

Asset Register

Asset Reference:

8.M.2

Inspection Date:

14.03.19

Location:

Plant room

Level:

08 - Eighth Floor

Equipment / Plant Ref:

Model Type:

Quantity:

Manufacturer:

Serial No:

Fire dampers to external louvre grille

Fuse link

2

Unknown

No.

Not available





Condition Rating:

Grade B

See section 1.4.1 for grading details

Priority Grading:

Priority 3

See Section 1.4.2 for details

Economic Life:

10 to 15

Year

From new/installation assuming regular servicing/maintenance

Predicated Future Life:

1 to 3

Years

Comments:

Operation of the fire dampers not carried out during inspection. Dampers required regular maintenance due to them being within chlorinated air stream.