Appendix 1

No	KPI - Yearly	14/15	Year End	15/16	Year End	16/17	Year end	17/18	Year End	18/19	Year End	19/20	up to P8
		Target	2014-15	Target	2015-16	Target	2016-17	Target	2017-18	Target	2018-19	Target	2019-20
R1	Customer satisfaction Repairs	88%	74.1%	88%	77.7%	89%	86.8%	89%	86.9%	90%	82.3%	90%	92.8%
R2	Recalls	1%	1.1%	1%	2.2%								
R2	Jobs passing post inspection					95%	90.1%	95%	90.6%	96%	95.7%	96%	97.4%
R3	Number of repairs completed on 1st visit	90%	86.6%	90%	93.4%	90%	93.9%	93%	93.2%	94%	95.3%	94%	94.1%
R4a	Repair completion times												
	Priority 0 & 00 (2 hours)	100%	97.9%	100%	97.9%	100%	99%	100%	100%	100%	100%	100%	100%
	Priority 1 (24 hours)	100%	98.7%	100%	98.9%	99%	99.8%	100%	100.0%	100%	100.0%	100%	100.0%
	Priority 2 (3 days)	98%	93.1%	98%	98.6%	98%	91.1%	99%	91.4%	99%	98.9%	99%	100.0%
	Priority 15 (15 working days)	97%	87.9%	97%	97.9%	99%	98.4%	98%	99.6%	98%	98.8%	98%	97.9%
	Priority 16 (60 working days)	99%	95.7%	99%	93.5%	100%	87.9%	99%	98.5%	99%	98.0%	99%	98.9%
R6	Appointments made and kept	95%	80.2%	95%	78.7%	95%	87.9%	95%	91.7%	96%	97.8%	96%	97.5%
V3	Voids-average number of days to complete	12 days	19 days	12 days	12.1 days	11 days	12.4 days	11 days	11.2 days	10 days	11.3 days	10 days	11.2 days
G1	Customer satisfaction Gas and Heating	88%	75.6%	88%	77.5%	89%	88.5%	89%	89.4%	90%	90.9%	90%	94.3%
G4	Gas service completions	100%	99.6%	100%	99.5%	100%	99.9%	100%	100.0%	100%	99.5%	100%	99.3%
G6	Gas Breakdowns completions timescales												
	Priority 0 & 00 (2 hours)		97.4%		100.0%		99.69%		92.50%		97.49%		99.00%
	Priority 1 (24 hours)		99.5%		99.8%		99.95%		98.20%		97.94%		99.90%
	Priority 2 (3 days)		96.8%		99.2%		99.91%		97.80%		94.40%		97.40%
	Priority 15 (15 working days)		98%		100%		99.27%		98.60%		98.15%		99.20%
	% of total breakdowns completed in target	98%	97.9%	98%	99.7%	98%	99.7%	98%	98.1%	98%	97.6%	98%	99.1%
G7	Gas - First time fix	95%	89.9%	95%	97.7%	95%	98.8%	95%	97.9%	96%	98.0%	96%	97.9%
C1	Customer Contact – calls abandoned	5%		5%	0.0429	5%	3.1%	5%	97.9%	5%	6.6%	5%	3.5%